

Table of Contents

Document Overview

Section 1: Stormwater Management Program.....	DO-1
Section 2: Sediment Control Program.....	DO-1
Section 3: County Road/Property Maintenance and Recycling Activities	DO-1
Section 4: NPDES Education Program.....	DO-1
Section 5: Illicit Connections Program.....	DO-2
Section 6: Geographic Information System and Databases.....	DO-2
Section 7: Watershed Planning and Restoration.....	DO-2
Section 8: Discharge Characterization and Assessment of Controls.....	DO-2
Section 9: Watershed and Restoration Monitoring.....	DO-3
Section 10: BMP Pollutant Load Reduction.....	DO-3
Section 11: Permit Administration, Legal Authority, and Fiscal Analysis.....	DO-3

Section 1: Stormwater Management Program

1.0 Permit Requirements.....	1-1
1.1 Introduction.....	1-2
1.2 Plan, and Variance and Fee-in-lieu Reviews.....	1-2
1.2.1 Plan Reviews.....	1-2
1.2.2 Variance and Fee-in-lieu Reviews.....	1-2
1.3 Approved Stormwater Management Facility Analysis.....	1-3
1.4 Inspections.....	1-7
1.5 Stormwater Management Facility Maintenance.....	1-8
1.6 Constructed Stormwater Management Facility Data Analysis.....	1-9
1.7 Summary.....	1-14

Section 2: Erosion and Sediment Control Program

2.0 Permit Requirement.....	2-1
2.1 Introduction.....	2-1
2.2 Program Analysis—Plans Review.....	2-2
2.3 Program Analysis—Inspection and Enforcement.....	2-2
2.3.1 Grading and Building Permits Issued.....	2-2
2.3.2 Inspections, Complaints and Enforcement.....	2-5
2.4 Program Analysis—Training Program.....	2-7
2.5 Summary.....	2-7

Section 3: Road Maintenance and Recycling Activities

3.0 Permit Requirements.....	3-1
3.1 Introduction.....	3-1
3.2 County Property Management.....	3-2
3.2.1 County Facility NPDES Permit Compliance.....	3-2
3.3 Storm Drain Cleaning Program.....	3-2
3.3.1 Storm Drain Cleaning Overview.....	3-2
3.3.2 Storm Drain Cleaning Data Analysis.....	3-3

3.3.3 Storm Drain Data by Watershed.....	3-6
3.3.4 Program Summary – Storm Drain Cleaning.....	3-8
3.4 Street Sweeping.....	3-8
3.4.1 Street Sweeping Overview.....	3-8
3.4.2 Street Sweeping by Watershed.....	3-10
3.4.3 Program Summary – Street Sweeping.....	3-12
3.5 Household Hazardous Waste (HHW).....	3-12
3.6 Fertilizer, Pesticide, and Deicing Statistics.....	3-16
 Section 4: NPDES Education Program	
4.0 Permit Requirements.....	4-1
4.1 Introduction.....	4-1
4.2 Education and Outreach Program Description.....	4-3
4.2.1 School Initiatives.....	4-3
4.2.2 Outreach to Homeowners, Citizen Groups, Businesses, and Landscape Managers.....	4-4
4.3 Environmental Education and Outreach Program Activity and Accomplishments.....	4-6
4.3.1 Schools: Activities and Accomplishments.....	4-9
4.3.2 Community Outreach: Activities and Accomplishments.....	4-19
4.4 Other Environmental Education and Outreach Initiatives.....	4-23
4.4.1 The Stream Watch Program.....	4-23
4.4.2 Watershed Association Restoration Planning and Implementation Grant Program.....	4-23
4.4.3 The Baltimore Watershed Agreement.....	4-24
4.4.4 Tree-Mendous Maryland Program in Baltimore County.....	4-24
4.4.5 The Baltimore County Forest Conservancy District Board.....	4-25
4.4.6 The Baltimore County Growing Home Campaign.....	4-26
4.5 Summary.....	4-27
 Section 5: Illicit Connection Program	
5.0 Permit Requirements.....	5-1
5.1 Introduction.....	5-1
5.2 Program Status.....	5-2
5.3 Analysis of Outfall Screenings.....	5-2
5.4 Illicit Connections Investigations and Corrections.....	5-7
5.5 Regional Illicit Connections Investigations and Complaint Database.....	5-16
5.6 Cooperative Project with the Center for Watershed Protection.....	5-17
5.7 Summary.....	5-17

Section 6: Geographic Information System and Databases	
6.0 Permit Requirements.....	6-1
6.1 Source Identification-Geographic Information System Data layers.....	6-2
6.1.1 Storm Drain System.....	6-2
6.1.2 Urban Best Management Practices.....	6-2
6.1.3 Impervious Surfaces.....	6-2
6.1.4 Monitoring Locations.....	6-3
6.1.5 Watershed Restoration.....	6-3
6.2 Databases.....	6-3
6.2.1 Chemical Data.....	6-3
6.2.2 Biological Data.....	6-3
6.2.3 Geomorphological Data.....	6-4
6.2.4 Illicit Discharge Detection and Elimination.....	6-4
6.2.5 Responsible Personnel Certificate Information.....	6-4
6.2.6 Grading Permit Information.....	6-4

Section 7: Watershed Planning and Restoration	
7.0 Permit Requirements.....	7-1
7.1 Introduction.....	7-2
7.2 Status of Watershed Management Plans.....	7-3
7.2.1 Water Quality Management Plans.....	7-3
7.2.2 Small Watershed Action Plans (SWAPs).....	7-4
7.3 Obtaining Pollution Reduction Numbers.....	7-6
7.3.1 Stream Restorations.....	7-6
7.3.2 Shoreline Enhancement Projects.....	7-6
7.3.3 Stormwater Retrofits.....	7-7
7.3.4 Community Reforestation Program.....	7-7
7.3.5 Activities of Volunteer Organizations.....	7-8
7.4 Capital Restoration Projects - Upper Western Shore Watersheds.....	7-8
7.4.1 Deer Creek.....	7-8
7.4.2 Prettyboy Reservoir.....	7-8
7.4.3 Loch Raven Reservoir Watershed.....	7-11
7.4.4 Lower Gunpowder Falls Watershed.....	7-14
7.4.5 Little Gunpowder Falls Watershed.....	7-16
7.4.6 Bird River Watershed.....	7-16
7.4.7 Gunpowder River Watershed.....	7-18
7.4.8 Middle River Watershed.....	7-20

7.5	Capital Restoration Projects - Patapsco/Back River Watersheds.....	7-21
7.5.1	Liberty Reservoir Watershed.....	7-21
7.5.2	Lower North Branch Patapsco River Watershed	7-22
7.5.3	Gwynns Falls Watershed.....	7-25
7.5.4	Jones Falls Watershed.....	7-27
7.5.5	Back River Watershed.....	7-30
7.5.6	Baltimore Harbor Watershed.....	7-33
7.6	Community Reforestation Program.....	7-35
7.7	Volunteer Organizations.....	7-37
7.8	Additional Restoration Efforts.....	7-38
7.8.1	Growing Home Campaign.....	7-38
7.8.2	Tree-Mendous Maryland Program in Baltimore County.....	7-39
7.8.3	Big Tree Sale.....	7-40
7.9	Pollution Reduction Tracking System.....	7-40
7.10	Impervious Surface Calculation.....	7-41
Section 8: Discharge Characteristics and Assessment of Controls		
8.0	Permit Requirements.....	8-1
8.1	Introduction.....	8-3
8.2	Scotts Level Branch Long-Term Monitoring.....	8-3
8.2.1	Monitoring Design.....	8-5
8.2.1.1	Flow Monitoring.....	8-5
8.2.1.2	Chemical Monitoring.....	8-6
8.2.1.3	Geomorphological Monitoring.....	8-7
8.2.1.4	Biological Monitoring.....	8-9
8.3	Scotts Level Branch Long-Term Site Monitoring Results.....	8-9
8.3.1	Flow Monitoring.....	8-9
8.3.2	Chemical Monitoring.....	8-12
8.3.2.1	Storm Event Monitoring Results.....	8-12
8.3.2.2	Baseflow Monitoring Results.....	8-13
8.3.2.3	Pollutant Load Calculations.....	8-14
8.3.3	Geomorphological Monitoring.....	8-16
8.3.4	Biological Monitoring Results.....	8-22
8.4	Windlass Run Monitoring – Stormwater Management Assessment.....	8-25
8.4.1	Stream Geomorphologic Assessment.....	8-26
8.4.2	Biological Monitoring.....	8-36
Section 9: Watershed and Restoration Monitoring		
9.0	Permit Requirements.....	9-1
9.1	Introduction.....	9-1
9.2	Chemical Monitoring Program.....	9-2
9.2.1	Baseflow Monitoring.....	9-2
9.2.2	Tidal Waters Monitoring Program.....	9-12
9.3	Stream Geomorphological Monitoring.....	9-18
9.3.1	Stream Restoration Project Monitoring.....	9-19
9.3.2	Stream Stability Assessments.....	9-20
9.3.3	Geomorphological Monitoring Summary.....	9-20

9.4	Biological Monitoring.....	9-20
9.4.1	Probabilistic Monitoring.....	9-21
9.4.2	Capital Improvements Projects Monitoring.....	9-31
9.4.3	Reference Site Monitoring.....	9-38
9.4.4	Submerged Aquatic Vegetation Monitoring Program.....	9-40
9.5	Status of Brook Trout in the Prettyboy Reservoir Watershed.....	9-41
9.5.1	Update of Activity in 2009.....	9-41
9.6	Stream Corridor Assessment.....	9-43
9.6.1	Introduction.....	9-43
9.6.2	Summary of Results.....	9-45
9.6.3	Summary of Erosion.....	9-47
9.6.4	Summary of Trash Dumping.....	9-48
9.6.5	Summary of Inadequate Buffer.....	9-50
9.6.6	Summary of Unusual Conditions and Comments.....	9-51
9.6.7	Summary of Fish Barrier.....	9-51
9.6.8	Summary of Pipe Outfall.....	9-53
9.6.9	Summary of In or Near Stream Construction.....	9-53
9.6.10	Summary of Representative Sites.....	9-53
9.6.11	Discussion.....	9-54
 Section 10: BMP Pollutant Load Reduction		
10.0	Permit Requirements.....	10-1
10.1	Introduction.....	10-1
10.2	Pollutant Load Calculations.....	10-2
10.3	New Nutrient Reduction and Impervious Cover Addressed Tracking Added This Year.....	10-5
10.4	Summary of Pollutant Reduction Programs.....	10-6
10.5	Progress in Meeting MS4 Impervious Restoration, TMDLs, and Maryland Tributary Strategies.....	10-10
10.5.1	MS4 Impervious Restoration.....	10-10
10.5.2	TMDL Progress.....	10-11
10.5.3	Maryland Tributary Strategies.....	10-12
10.6	Summary.....	10-13
 Section 11: Permit Administration, Legal Authority, and Fiscal Analysis		
11.0	Permit Requirements.....	11-1
11.1	Permit Administration.....	11-1
11.2	Legal Authority.....	11-2
11.2.1	Stormwater Management.....	11-2
11.2.2	Chesapeake Bay Critical Area.....	11-3
11.2.3	Soil Erosion and Sediment Control.....	11-3
11.3	Fiscal Analysis.....	11-3

List of Tables

1-1	Fee-in-lieu money received in 2009.....	1-3
1-2	Approved Stormwater Management Facilities by Watershed Through 2009.....	1-4
1-3	SWM Inspections 2009	1-7
1-4	Stormwater Facility Maintenance Visits by Type 2009.....	1-8
1-5	SWM Pond Maintenance Activities for Calendar Year 2009.....	1-9
1-6	Constructed SWM Facility Drainage Area Land Use (Acres) by Watershed through Calendar Year 2009.....	1-10
1-7	Pollutant Loads to Constructed SWM Facilities by Watershed.....	1-10
1-8	Percent Removal Efficiency of BMPs.....	1-11
1-9	Total Phosphorus Removal by SWM Facility Type and Watershed.....	1-12
1-10	Total Nitrogen Removal by SWM Facility Type and Watershed.....	1-12
1-11	Impervious Cover Addressed by All SWM and Advanced SWM	1-13
2-1	Number of Grading Permits and Acreage of Disturbance by Watershed for 2009.....	2-2
2-2	Number of Building Permits by Watershed Approved in 2009.....	2-3
2-3	Number of Grading and Building Permits by Year.....	2-4
2-4	Sediment Control Inspection Data for 2009.....	2-6
3-1	NPDES Permit Compliance Status.....	3-2
3-2	Removal Rates of Vac-Con Inlet and Pipe Cleaning by Year.....	3-3
3-3	2009 Material Removed in Cubic Yards by Watershed.....	3-6
3-4	2009 Storm Drain Cleaning Program Pollutant Removal (Pounds) and Impervious Urban Acres Treated	3-8
3-5	Annual Street Sweeping Summary.....	3-9
3-6	2009 Street Sweeping Program – Tons Removed from Watersheds.....	3-11
3-7	2009 Street Sweeping Program Pollutant Removal (Pounds) and Impervious Urban Acres Treated	3-11
3-8	Household Hazardous Waste Recycled (2003-2009).....	3-13
3-9	2009 County Agency Fertilizer, Pesticide, and Deicing Materials Used (in Pounds).....	3-17
3-10	Annual Fertilizer, Pesticide and Deicing Materials Used By County Agencies (in Pounds).....	3-17

4-1	NPDES Public Environmental Education Topics Addressed through County Initiatives, by Basin, 2009.....	4-7
4-2	Education Outreach Conducted for Residents of the County and Region by Watershed Audience, 2009.....	4-8
4-3	Education Presentations, Distributions and Events by Type of Audience, 2009.....	4-8
4-4	<i>Maryland Green Schools</i> by Jurisdiction 1999-2009.....	4-9
4-5	School and Community Environmental Education Projects Implemented in County Watershed Basins by the New and Recertifying MD Green Schools (public and private) in Baltimore County, 2009.....	4-10
4-6	Number of Participants in MD Green School Program in Baltimore County, 2009.....	4-14
4-7	Tree Plantings on Baltimore County School Property, Fall 2009.....	4-18
4-8	Community and Business Partnerships Supporting Baltimore County’s Public Schools recognized as MD Green Schools, 2009.....	4-21
4-9	Presentations, Participants and/or Audience, and Materials, 1994-2009....	4-22
5-1	Major Outfalls by Watershed and Priority Classification.....	5-3
5-2	Non-prioritized outfalls by Watershed.....	5-4
5-3	Complaints Processed from January 1, 2009 through December 31, 2009..	5-7
7-1	Status of Watershed Management Plans.....	7-3
7-2	SWAP Schedule.....	7-5
7-3	Percent Removal Efficiency of BMPs.....	7-7
7-4	CBP Nutrient Loading Rates.....	7-7
7-5	Prettyboy Reservoir Watershed – CIP Status.....	7-9
7-6	Loch Raven Reservoir Watershed – CIP Status.....	7-12
7-7	Lower Gunpowder Falls Watershed – CIP Status	7-14
7-8	Little Gunpowder Falls Watershed – CIP Status	7-16
7-9	Bird River Watershed – CIP Status.....	7-17
7-10	Gunpowder River Watershed – CIP Status.....	7-19
7-11	Middle River Watershed – CIP Status.....	7-20
7-12	Patapsco River Watershed – CIP Status.....	7-23
7-13	Gwynns Falls Watershed – CIP Status.....	7-26
7-14	Jones Falls Watershed – CIP Status.....	7-28
7-15	Back River Watershed – CIP Status.....	7-31
7-16	Baltimore Harbor Watershed – CIP Status.....	7-34
7-17	Baltimore County Reforestation Projects by Calendar Year.....	7-36
7-18	Baltimore County Reforestation Projects by Watershed through 2009.....	7-36
7-19	Watershed Associations’ Projects Resulting in Nutrient Reductions.....	7-37
7-20	Watershed Association Projects Nutrient Reductions by Watershed.....	7-38
7-21	Number of Growing Home Trees Planted in the Upper Western Shore Basin.....	7-38

7-22	Number of Growing Home Trees Planted in the Patapsco/Back River Basin.....	7-39
7-23	Growing Home Trees Associated Nutrient Reductions.....	7-39
7-24	Baltimore County Impervious Area by Watershed – Changes Between 1997 and 2005.....	7-41
7-25	Baltimore County and Maryland State Highway Impervious Acreage.....	7-42
7-26	Nutrient Reduction and Impervious Acreage Addressed by Completed Capital Projects.....	7-43
7-27	County Impervious Cover Addressed by the Current SWAPs.....	7-43
8-1	Scotts Level Branch, Powder Mill Run, and Upper Gwynns Falls Information	8-5
8-2	USGS Gage Information.....	8-5
8-3	Precipitation Data Analysis for Calendar 2009.....	8-9
8-4	2009 Precipitation Amount, Intensity, and Duration by Category	8-10
8-5	Seasonal Precipitation and Runoff Characteristics.....	8-11
8-6	Regression Equations Relationship Between Discharge (CFS) and Pollutant Concentrations.....	8-12
8-7	2009 Daily Baseflow Pollutant Loads for Scott’s Level Branch Sites	8-13
8-8	Pollutant Load Characteristics for USGS gaged site (SL-01) Calendar Year 2009.....	8-14
8-9	Scotts Level Branch Cross Sections - Annualized Cut and Fill Amounts..	8-17
8-10	Scotts Level Branch Stream Channel Changes Over Time.....	8-19
8-11	Pollutant Load Estimates- Comparison between Water Quality Monitoring and Geomorphology for Scotts Level Branch, 2006 - 2009.....	8-20
8-12	Powder Mill Run Cross Sections - Cut and Fill Amounts.....	8-21
8-13	Powder Mill Run, 2007-2009 and 2005-2009 Stream Channel Changes....	8-22
8-14	Windlass Run Cross Sections - Cut and Fill Amounts.....	8-35
8-15	Windlass Run Stream Channel Changes Over Time.....	8-36
9-1	Site Codes and the Associated Tidal Water body.....	9-14
9-2	Summary of Capital Improvements Projects Monitoring Reports Submitted for 2009.....	9-19
9-3	BIBI Metrics.....	9-21
9-4	BIBI Score Distribution by Watershed (% by Category).....	9-22
9-5	Watershed Biological Condition Using Percent Stream Mile Method.....	9-25
9-6	Stream Restoration Biological Monitoring Site Locations.....	9-31
9-7	Biological index values for all Minebank Run stations, 2009.....	9-33
9-8	Biological index values for Redhouse Run stations, 2009.....	9-37
9-9	Spring Branch Fish Data.....	9-37
9-10	Reference Site Locations.....	9-39
9-11	Biological metrics and index values for Reference Sites, 2009.....	9-39
9-12	SAV Standards and Baltimore County SAV Monitoring Results (2007-2009).....	9-41
9-13	Prettyboy Reservoir brook trout and thermal monitoring stations, 2009....	9-43
9-14	Total Stream Miles and Stream Miles Surveyed, by Subwatershed.....	9-46

9-15	Summary of Results From Gunpowder Falls.....	9-46
9-16	Listing of Information by Site.....	9-55
9-17	Listing of Sites by Problem Category.....	9-55
10-1	Status of TMDLs and TMDL Reduction Requirements for Urban Stormwater.....	10-1
10-2	Nitrogen Per Acre Pollutant Rate, MDE Segment and CBP Segment	10-3
10-3	Phosphorus Per Acre Pollutant Rate, MDE Segment and CBP Segment ...	10-4
10-4	2005 Land Use (Acres).....	10-4
10-5	Watershed Nitrogen Loads- Pounds and Percentage.....	10-5
10-6	Watershed Phosphorous Loads Pounds and Percentage.....	10-5
10-7	Pollutant Removal (Pounds) by Upper Western Shore Watersheds Attributed to BMP's.....	10-7
10-8	Pollutant Removal (Pounds) by Patapsco/Back River Watersheds Attributed to BMPs.....	10-9
10-9	Impervious Cover Addressed by Water Quality Improvement Efforts to Date.....	10-11
10-10	Progress in Meeting Nutrient TMDLs Where Developed.....	10-12
10-11	Upper Western Shore Urban Tributary Strategy.....	10-13
10-12	Patapsco/Back River Urban Tributary Strategy.....	10-13
10-13	Tributary Strategy Urban Non-point Nutrient Load Reduction Process.....	10-13
11-1	Major NPDES Program Tasks and Responsible Baltimore County Agencies.....	11-1
11-2	NPDES Operating Budget.....	11-3
11-3	Capital Budget and Program.....	11-3
11-4	Baltimore County Environmental Capital Improvement Program- Fiscal Year 2010 & 2011.....	11-4
11-5	Baltimore County Environmental Capital Improvement Program- Fiscal Year 2012 & 2013.....	11-4
11-6	Baltimore County Environmental Capital Improvement Program- Fiscal Years 2014 & 2015.....	11-5

List of Figures

1-1	Number of Approved SWM Facilities by Watershed— Through Calendar Year 2009.....	1-6
1-2	Acreage Served by Approved Private SWM Facilities by Watershed Through Calendar Year 2009.....	1-6
1-3	Acreage Served by Approved Public SWM Facilities by Watershed Through Calendar Year 2009.....	1-7
2-1	Acres of disturbance through approved grading permits by watershed for 2009.....	2-3
2-2	Number of building permits issued in 2009 by watershed.....	2-4
2-3	Approved Grading and Building Permits for the Period 1998 – 2009.....	2-5
2-4	The number of sediment control enforcement actions by month for the calendar year 2009.....	2-6
2-5	Number of sediment control inspections and the total number of inspections by month for the calendar year 2009.....	2-7
3-1	Summary Report for Inlets.....	3-4
3-2	Annual Inlet Debris Removal Rates.....	3-4
3-3	Summary Report for Pipes.....	3-5
3-4	Annual Pipe Debris Removal Rates.....	3-5
3-5	Miles of Street Swept, Tons of Material Removed and Tons/Miles Swept	3-10
3-6	Household Hazardous Wastes Recycling of Flammables, Gasoline, and Pesticides from 1998 to 2009.....	3-16
3-7	Waste Oil and Anti-freeze Recycled from 1991 through 2009.....	3-16
3-8	Trends in Annual Fertilizer and Pesticide Used by County Agencies.....	3-18
3-9	Trends in Annual Deicing Material Used by County Agencies.....	3-18
5-1a	Major Outfall Prioritization.....	5-5
5-1b	Minor Outfall Prioritization.....	5-6
5-2a	Major Outfall Screening Priority Distribution.....	5-7
5-2b	Major Outfall Screening Priority Distribution.....	5-7
5-3a	Major Outfalls Number of <i>quantitative</i> problems detected.....	5-8
5-3b	Minor Outfalls Number of <i>quantitative</i> problems detected.....	5-9
5-4a	Major Outfalls Number of <i>qualitative</i> problems visually observed.....	5-10
5-4b	Minor Outfalls Number of <i>qualitative</i> problems visually observed.....	5-10
5-5	Involvement of the Regional Programs in the Investigation of Illicit Connections.....	5-16
7-1	Baltimore County SWAPs.....	7-5
7-2	Capital Projects in the Prettyboy Watershed.....	7-10
7-3	Capital Projects in the Loch Raven Watershed.....	7-13
7-4	Capital Projects in the Lower Gunpowder River Watershed.....	7-15
7-5	Capital Projects in the Bird River Watershed.....	7-18
7-6	Capital Projects in the Gunpowder River Watershed.....	7-19

7-7	Capital Projects in the Middle River Watershed.....	7-21
7-8	Capital Projects in the Patapsco River Watershed.....	7-24
7-9	Capital Projects in the Gwynns Falls Watershed.....	7-27
7-10	Capital Projects in the Jones Falls Watershed.....	7-29
7-11	Capital Projects in the Back River Watershed.....	7-32
7-12	Capital Projects in the Baltimore Harbor Watershed.....	7-35
7-13	Number of trees obtained through the Tree-Mendous Maryland Program with technical assistance and free tree delivery by DEPRM between 1990 and 2008.....	7-40
8-1	Subwatersheds to be used in the Paired Watershed Monitoring Design....	8-4
8-2	Scotts Level Branch Chemical Monitoring Locations.....	8-6
8-3	Scotts Level Branch Geomorphological and Biological Monitoring Site Locations.....	8-8
8-4	Powder Mill Run Geomorphological and Biological Monitoring Sites.....	8-8
8-5	Calendar year 2009 Daily Precipitation and Discharge.....	8-11
8-6	Scotts Level Branch Geomorphological Cross Section 1 Overlay showing net deposition especially on the right channel side between the 2008 and 2009 surveys.....	8-17
8-7	(a) Scotts Level Branch and (b) Powder Mill Run IBI Scores	8-23
8-8	(a) Scotts Level Branch and (b) Powder Mill Run PHI Scores	8-24
8-9	Windlass Run Aerial Photograph Showing Monitoring Station Locations.	8-27
8-10	Orthophotograph of Windlass Run watershed, 1995.....	8-29
8-11	Windlass Run watershed orthophotograph, 2002.....	8-30
8-12	Windlass Run orthophotograph, 2005.....	8-31
8-13	Windlass Run orthophotograph, 2007.....	8-32
8-14	Summary of cross-sectional changes in Windlass Run during entire study period.....	8-34
8-15	Summary of pebble counts in Windlass Run during entire study period...	8-35
8-16	Windlass Run BIBI Scores.....	8-37
9-1	Patapsco/Back River Basin – Baseflow Monitoring Sites.....	9-3
9-2	Gunpowder Basin/Deer Creek – Baseflow Monitoring Sites.....	9-4
9-3	Frequency distributions by concentration for Total Copper and Dissolved Copper for the 2009 Patapsco/Back River Basin samples.....	9-5
9-4	Duncan’s Multiple Range Test results for Total Kjeldahl Nitrogen, Nitrate/Nitrite, Sodium, Total Nitrogen.....	9-6
9-5	Baseflow Dissolved Copper, Nitrate/Nitrite, Total Nitrogen, Chloride, Sodium and Total Phosphorus for sampling years 2003, 2005, 2007, and 2009.....	9-6
9-6	Baseflow Rolling Averages for Dissolved Copper, Nitrate/Nitrite, Total Nitrogen, Chloride, and Total Phosphorus for sampling years 2003, 2005, 2007, and 2009.....	9-7
9-7	Baseflow Total Nitrogen Mean Concentrations for Monitoring Years 2008 (Gunpowder Basin) and 2009 (Patapsco/Back River Basin).....	9-10

9-8	Baseflow Total Phosphorus Mean Concentrations for Monitoring Years 2008 (Gunpowder Basin) and 2009 (Patapsco/Back River Basin).....	9-11
9-9	Tidal Waters Monitoring Site Locations.....	9-13
9-10	Duncan’s Multiple Range Test results for Total Suspended Solids, Total Kjeldahl Nitrogen, NO ₂ /NO ₃ , Total Nitrogen, and Total Phosphorus.....	9-15
9-11	Pollutant Between Year Variation by Site.....	9-16
9-12	Tidal Monitoring Rolling Averages for TSS, Dissolved Copper, TKN, Nitrate/Nitrite, Total Nitrogen, and Total Phosphorus for sampling years 2002 through 2009.....	9-16
9-13	Means and one standard deviation of BIBI scores for Patapsco/Back River watersheds between 2003 and 2009.....	9-24
9-14	Means and one standard deviation of BIBI scores of Gunpowder Falls/Deer Creek watersheds between 2004 and 2008.....	9-24
9-15	Probabilistic Biological Monitoring results for 2006 and 2007.....	9-26
9-16	Probabilistic Biological Monitoring results for 2008 and 2009.....	9-27
9-17	BIBI rolling averages for (a) Patapsco/Back River and (b) Gunpowder/Deer Creek probabilistic monitoring sites between 2003 and 2009.....	9-28
9-18	Mean BIBI scores for (a) Patapsco/Back River and (b) Gunpowder/Deer Creek Sentinel Sites between 2003 and 2009.....	9-29
9-19	Mean BIBI scores for sentinel sites by watershed in the (a) Patapsco/Back River and (b) Gunpowder/Deer Creek between 2003 and 2009.Falls/Deer Creek watersheds.....	9-30
9-20	Minebank Run Biological Monitoring Stations.....	9-32
9-21	Biological index values at the downstream, unrestored control (MNBK-1); the unrestored control (JB-1); restored Phase II (MNBK-2 and MNBK-4); and restored Phase I (MNBK-7) stations from beginning of monitoring to present.....	9-34
9-22	Woodvalley Biological Monitoring Station Locations.....	9-35
9-23	Benthic and Fish IBI and Physical Habitat Index Values for (a) WDVL-1 (restored) and (b) WDVL-3 (control).....	9-36
9-24	Benthic IBI Values for Spring Branch biological monitoring stations.....	9-38
9-25	Baltimore County SAV Monitoring Program – Trends in % Coverage....	9-42
9-26	Map of Prettyboy Subwatersheds.....	9-44
9-27	Map of the Streams Surveyed.....	9-45
9-28	Potential Stream Problems.....	9-47
9-29	Severity Distribution of Sites.....	9-47
9-30	Map of Erosion Severity and Location.....	9-48
9-31	Severity Distribution of Sites.....	9-49
9-32	Map of Trash Dumping Severity and Location.....	9-49
9-33	Severity Distribution of Sites.....	9-50
9-34	Map of Inadequate Buffer Severity and Location.....	9-51
9-35	Severity Distribution of Sites.....	9-52
9-36	Map of Fish Barrier Severity and Location.....	9-52
9-37	Map of Representative Site Locations.....	9-54

List of Exhibits

4-1	Baltimore County’s “ <i>Quick Guide</i> ” for Citizens, Organizations, and Businesses, Page 1.....	4-29
4-2	Baltimore County’s <i>Maryland Green Schools and Green Centers</i> , 1999-2009.....	4-31
11-1	Department of Environmental Protection and Resource Management Table of Organization for FY2011.....	11-5
11-2	Department of Environmental Protection and Resource Management Staff Organizational Chart Effective 2010.....	11-8

List of Appendices

1-1	Public Stormwater Facility Maintenance by Type for Calendar Year 2009.....	1-15
2-1	List of Individuals Receiving Certification.....	2-9
2-2	Baltimore County Sediment Control Delegation Approval.....	2-10
4-1	Presentations, Distributions, and Events, by Watershed, 2009.....	4-32
4-2	Education Program: Recycling Presentations, 2009 Accomplished by Baltimore County Department of Public Works, Recycling Division.....	4-42
8-1	Regression Analysis Graphs.....	8-39
9-1	Baseflow Monitoring Sites by Watershed.....	9-57
9-2	Baseflow Water Quality Data by Site.....	9-58
9-3	Tidal Waters Chemical Monitoring Results.....	9-67
9-4	Results of 2009 Probabilistic Monitoring.....	9-70
11-1	Stormwater Management Regulatory Changes Bill 25-10.....	11-9